

Oil Field Environmental Incident Summary

Incident: 20141219160359 **Date/Time of Notice:** 12/19/2014 16:03
Responsible Party: ENDURO OPERATING, LLC
Well Operator: ENDURO OPERATING, LLC
Well Name: STONEVIEW-STONEWALL UNIT 1311
Field Name: STONEVIEW **Well File #:** 14917
Date Incident: 12/19/2014 **Time Incident:** 15:05 **Facility ID Number:**
County: DIVIDE **Twp:** 160 **Rng:** 95 **Sec:** 11 **Qtr:**
Location Description:

Submitted By: Scott Hunskor **Received By:**
Contact Person: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

No release

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in well head, Shut in tanks (Water and Oil). Put fire out and let cool down

Wastes Disposal Location: No release

Agencies Involved: Local Fire Department

Updates

Date: 12/19/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire on location. Nothing released off location according to the report. NDIC retains oversight.